



November 1, 2013

**CARB Advisory 405-B – Response to Winter Season  
In-Station Diagnostics (ISD) Pressure Alarms**

Enclosed is a copy of California Air Resources Board (CARB) Advisory 405-B (Response to Winter Season In-Station Diagnostics Pressure Alarms). The District is re-issuing this advisory to remind GDF operators of the procedures for clearing ISD alarms from November 1, 2013, to March 1, 2014.

If you have any questions relating to CARB Advisory 405-B or any other vapor recovery related matters, please contact Randy Smith at (858) 586-2677 or Matthew Allison at (858) 967-9766.

RGSm:MA:jlm

Enclosure